



MAY 2020 UPDATES

MAINTENANCE WORK

DITCH	LOCATION	DESCRIPTION OF WORK PERFORMED
102-D2	Blanchett	Slope repair
202-E	College St. to Calder Ave.	Removed silt from 11,500 feet of ditch
405	Estates of Fannett North to Bayou Din	Silt removal.
407	North Side of Green Acres	Silt removal.
500 NFW	IH-10 @ Taylor's Bayou	Cut swale ditches.
505-F	West Clubb Rd.	Relocate 500 feet of fencing.
604-A	Lawhon Rd.	Repair pipe washout.
605	S. Pine Island Rd.	Mowing 12,000 feet ditch top and slopes with long-stick.
605-E1	S. Pine Island Rd.	Blade dirt and clean up ditch top.
1002	Tram Rd.	Clean out concrete-lined section.
1206-A	Westbury Rd.	Relocate 800 feet of fencing and clear trees.
407-A, B, C, E, E, F	Green Acres Subdivision	Weedeated approximately 24,000 feet of ditch top in areas with limited equipment access.

MAINTENANCE MOWING

EQUIPMENT USED	DITCHES MOWED
ZTRs	001-A, 002, 003, 004-A, 004-B, 004, 100-J, 100-X, 104-B, 105, 106-B, 106, 107-B, 107-C, 107, 108-B, 108, 109, 111-B, 112, 117, 118-A, 118-B, 118, 120-X, 120, 121, 122, 123, 200-A, 200-B, 202-A, 202-B, 202-BX, 202-C3, 202-D, 202-E, 202-E1, 202-X, 202, 407-A, 407-B, 407-C, 407-D, 407, 905-A, 905, 1004-A1, 1203-A, 1203-A1, 1203-B, 1203-B1, 1204-C, 1204-D1, 1204
Tractors	001-A, 001, 002, 100-J, 100-X, 104-B, 105, 106, 107-B, 107-C, 107, 108-B, 108, 109-A, 109, 111-B, 118-A, 118, 121, 200-A, 200-B2, 202-A, 202-B, 202-BX, 202-C3, 202-D, 202-E, 202-E1, 202-X, 202, 300, 400, 402, 405-A, 405-A1, 405-A1A, 4005, 407, 408, 500-XA, 500, 502-E, 502, 504, 505-*A, 505-A1, 505-C, 5005, 511-B, 511, 600, 602-D, 602-F, 602, 604-A1, 604-B, 604, 605, 607-A4, 607-B1, 607-D, 607-J, 607-K, 607, 611-D, 611, 617, 1002, 1003, 1004-A1, 1004, 1006, 1203-A, 1203, 1204-B, 1204, 1205-A, 1205
Long-stick	<p><u>Mowing</u>: Ditch 605 - approximately 3700' of ditch top, slope on both sides, and bottom. Ditch 607 - approximately 6800' of ditch top, slope on both sides, and bottom. Ditch 600 - approximately 1600' of ditch top and slope on one side.</p> <p><u>Slashing</u>: Ditch 600 - approximately 4500' of ditch top and slope on one side. Ditch 400 - approximately 4350' of ditch slope on one side.</p>

HERBICIDE SPRAYING

DITCHES SPRAYED
001-A2, 001, 002, 004, 100-A, 100-D, 104-A, 104-A1, 104, 106, 108-A1, 108-B, 117, 118-B, 118, 121, 122-A, 122, 123, 202-B, 202-E, 202-E1, 405-A, 405-A1, 407-A, 407-B, 407-C, 407-D, 407-E, 407-F, 407-F1, 511-B, 511-C, 511, 900, 901-B, 902, 903, 904, 905-A, 905, 1002-A1, 1002-A2, 1002-B, 1002-D, 1002-E, 1002, 1004-A1, 1004-B1, 1004-C, 1004, 1008, 1202-A, 1202-D, 1203-A, 1203-A1, 1203-B, 1203-B1, 1203, 1204-C, 1204-D, 1204-D1, 1204-G, 1205-A, 1205

PROJECT WORK

DITCH	LOCATION	DESCRIPTION OF WORK PERFORMED
118	Daisy Dr. Outfall	Set 160 feet of 60-in pipe and constructed catch basin.
500-A4	Garner Road Outfall	Installed 90 feet of 60-in pipe.
500-A4A	Garner Road Outfall	Installed 60 feet of 60-in pipe.
500-A3	Garner Road Outfall	Installed 120 feet of 24-in pipe.
511-B	Catherine & Cole Streets	Set 40 feet of 24-in pipe.
600	S. China Rd.	Hydromulched levee on NRCS project.
600	Deer Camp Rd.	Replaced 24-in pipe with 60-in pipe and screw gate on Green Pond Levee.
709 709-A	Hamshire Rd.	Removed pipe and open LNVA canal for drainage.
8202	GIWW	Installed Outfall Structure #2/saltwater barrier.

Ditch 8202 - Saltwater Barrier and Water Control Structure at GIWW



Ditch 405 -Green Acres Area – Marsh Master



Ditch 1002 @ Tram Road



Ditch 118 – Daisy Drive Outfall



Ditch 709-A - Hamshire Road Area

