



## SEPTEMBER 2021 MAINTENANCE UPDATES

### TRACTORS AND MOWERS

EQUIPMENT USED	DITCHES MOWED
ZTRs	001, 001-A2, 002, 003, 004, 004-A, 004-B, 104-B, 110-E, 900, 901-B, 901-B1, 902, 903, 904, 1002, 1004, 1002-A, 1002-A1, 1004-A, 1004-A1, 1004-B, 1004-B1, 1004-C, DD6 COMPLEX
Tractors	001, 001-A2, 002, 004, 004-A, 004-B, 100, 104, 104-B, 106, 106-B, 107, 107-B, 107-C, 121, 123, 123-A1, 123-A1A, 123-B, 123-C, 123-D, 200, 202-E, 202-E1, 407, 407-A, 600, 804, 804-B, 804-B1, 804-C, 804-C1, 804-D, 804-D1, 804-D3, 804-D4, 900, 901-B, 901-B1, 902, 903, 904, 1000, 1002, 1002-A, 1002-A1, 1002-D, 1003, 1004, 1004-A, 1004-A1, 1004-B, 1004-B1, 1004-C, 1100, 1101-A, 1101-C, 1101, 1102, 1105, 1109, 1207-A, 8101, BYR-T1, Pond A, Pond C, WCDP

### LONG-STICK AND MARSH MASTER MOWING

DITCH	LOCATION	DESCRIPTION OF WORK PERFORMED
104-B	Avenue A	Marsh Master® Mowing – 9 acres
101-XA1	Hwy-365	Long-stick Mowing 10,700 feet
803-A	Thompson Rd.	Marsh Master® Mowing – 4,000 feet
100-D Pond	Milam	Marsh Master® Mowing – 7 acres
117 Pond	Arthur St.	Marsh Master® Mowing – 14 acres

### LONG-STICK SLASHING

DITCH	LOCATION	DESCRIPTION OF WORK PERFORMED
609	Railroad St.	220 feet of trees/underbrush
209	Hwy-90	1,100 feet of trees/underbrush
503-A	Patterson Rd.	1,700 feet of trees/underbrush
505-A	IH-10	2,000 feet of trees/underbrush
505-a1	IH-10	2,400 feet of trees/underbrush

## HERBICIDE SPRAYING

### DITCHES SPRAYED

001, 002, 003, 004, 010, 106, 106-B, 107, 107-B, 107-C, 121, 121-A, 123, 123-A1, 123-A1A, 123-B, 123-F, 123-XA, 405-A1A, 407, 900, 901-B, 901-B2, 902, 903, 903-A, 904, 905-B, 1000, 1000-A1, 1002, 1002-A, 1002-A2, 1002-B, 1002-D, 1002-E, 1003, 1004, 1004-A, 1004-A1, 1004-B, 1004-B1, 1100, 1101, 1101-A, 1101-B, 1101-B1, 1101-C, 1109, 1110, 1111, 1112, 1206-A, 1207-A, 8003-B2, 8003-C, RWD

## COMPLETED MAINTENANCE WORK

DITCH	LOCATION	DESCRIPTION OF WORK PERFORMED
500	Johnson Rd.	Repair washout
500-A	Craigen Rd.	Cleaned 700 feet of ditch
505-A	IH-10	Set tank car
571	LaBelle Rd.	Cleaned 5,500 feet of ditch
701	Bill Gaulding Rd.	Cleaned 9,800 feet of ditch
804	Thompson Rd.	Washout repair
602-B	Lawhon Rd.	Cleaned 3,400 feet of ditch
1207-A	Hwy-326	Washout repair Installed 60-in x 40-ft HDPE pipe